


Fig. 2









Fig. 4










Fig. 8





Fig. 9






Fig. 11




Fig. 12




Fig. 13






Fig. 14








Fig. 17





Fig. 18






Fig. 20




Fig. 21




Fig. 22




Fig. 23




Fig. 24




Fig. 25




Fig. 26

Đ

Höfte et al. Case 9177 "Cleaning Implement"




Fig. 27